<b>Work Orde</b> July 08, 2009-11	er ID 50099 1:14:36 AM									Page	1
	D3145-1		Accept				S	etup Sta	rt		
	B Bracket							Sto	p .		
Start Date:	7/10/2009 Start Qty	: 5.00		Cust Item I	D:						
Required Date:	7/31/2009 Req'd Qty	y: 5.00		<b>Customer:</b>							
Reference:											
Approvals:	Process Plan:	Date:	Tooling:	Da	ate:	_	R	un Sta			•
	QC:	Date:	SPC (Y/N):	Da	ate:			Sto	p		
Sequence ID/ Work Center II	Operation Descriptio		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	
Draw Nbr	Revision Nbr										
D3145	Rev B										
100			0.00								
D. J.	BAND SAW		0.00	- 1 1	,			_0_			-
Bandsaw Jeaspa Bandsaw		<b>Memo</b> Cut blanks: (2.00" x 2.00") x 4.500	0.00 o" (+0.030/-0.00) Long Bar	and oalo	7109	1	(5)				
			J. 1								
110			0.00								6
	HAAS CNC	VERTICAL MACHINING #1		The	1		(5)	3			Pic
HAAS I		Memo	0.00	7711-08/	07/20						
HAAS CNC vertical	machine #1	Machine per Folio FA318 and Dw	g D3145□Deburr and Tumble								
120	QC2- Inspect	parts off machine FAI/FAIB	0.00	7/20			(2)	,			
OC	,	Mama	0.00	1-1 pg		•	$\overline{\mathcal{C}}$	_0_			-

**Quality Control** 



Dart	Aerospace	Ltc
W//O.		

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
		·								
-,										

art	No:	<u>ע</u>	<u> </u>	70	· —	 PAR	#:

NA Fault Category: Mach

NCR Yes No DQA: Date: 09.01.2 |

QA: N/C Closed: Date: 05.08.17

Resolution: \_

Sceap

Disposition: See PO.

QA: N/C Closed:

NCR:5	0099	We						
DATE	STEP	Description of NC Section A	Initial	Corrective Action Section B Action Description	Verification	Approval	Approval	
		3 ports scupe parts ocoped	Chief Eng	Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
0507.14	110	and of the vise during machine, and at the same time the set but come loose from vibration.		Scrap i clestray Qty 3 Replace x 3 M 17/24 Ensure parts are snug as a bug	09/07/14	<b>A</b>		
<i>d</i> <sub>1</sub> , 1	1,0	bult come bose from vibration. RC' process	Suz	Ensure parts are snug as a bug	7,07	20) 3	POSICUZ	6307.14
					14			
		•						

M112148

MAOU! P

Memo

START TIME:

ና՝ 3৩ዾ⊌FINISH TIME:

Powdercoat

Powder Coating

0.00

\_OVEN TEMPERATURE

09-07-16

Dart	<b>Aeros</b>	pace	Ltd
------	--------------	------	-----

STEP	PR	WO	RK ORDER CHANGE	ES				
STEP	PR							
		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
					osed:		Date: _	
		WORK ORDE	R NON-CONFORMA	NCE (NCF	R)			
STEP	Description of NC			Section B Verification			Approval	Approval
	Section A	Chief Eng	Chief Eng	Date	Secti	ion C	Chief Eng	QC Inspector
		Resolution:	Resolution: Disposition  WORK ORDE  STEP Description of NC Section A Initial	Resolution:	Resolution: Disposition: QA: N/C CI  WORK ORDER NON-CONFORMANCE (NCR  STEP Description of NC Section A	Resolution: Disposition: QA: N/C Closed:  WORK ORDER NON-CONFORMANCE (NCR)  STEP Description of NC Section A Corrective Action Section B Verific Section A Section B Sign & Section A Section Description Sign & Section A Section Description Sign & Section A Section Description Sign & Section Descript	Resolution: Disposition: QA: N/C Closed:  WORK ORDER NON-CONFORMANCE (NCR)  STEP Description of NC Section A Corrective Action Section B Verification Section C Section C	STEP Description of NC Section A Initial Action Description Sign & Section C

170

Identify as per dwg & Stock Location:

0.00

Packaging

Memo

0.00

Packaging

180

QC21- Final Inspection - Work Order Release

0.00

QC

Memo

0.00

**Quality Control** 

69107/20 Ad

Page 3

Insp.

Stamp

-							
_		A				Ltd	
	21	ΛΟΙ	~~	$\mathbf{n}$	^_	1 1/1	
_	aıı	~	us	va	LE	-u	

W/O:		WORK ORDER CH	WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
-												
Part No	:	PAR #: Fault Category:	NCR: Yes	No DQ	<b>\</b> :	Date:						

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B	<u></u>	Verification	Annuaral	A		
DATE	STEP	Section A	Initial Action Description Sign & Chief Eng Chief Eng Date			Section C	Approval Chief Eng	Approval QC Inspector		
	}									

July 08, 2009 11:14:36 AM

Work Order ID: 50099

Parent Item:

Comments:

D3145-1RevB

Parent Item Name: Bracket

**Start Date:** 7/10/2009

Required Date: 7/31/2009

Start Qty: 5.00

Required Qty: 5.00

Component Item ID/	Replacement	Mfg/	Bin Primary	Last	Route	Unit of	Qty on	Remaining	Qty	Date	Status
Item Name	Item ID	Purch	Item Location	Location	Seq ID	Measure	Hand	Qty To Pick	Issued	Issued	
M6061T6B2.000X02.00 0		Purchased	No		100	f	30.0000	2.0174	.*		

6061-T6 Bar 2.00 x 2.00

Warehouse	Loc Oty	Loc Code	
<b>Location</b>			
Main Warehouse			
MAT	30		<u> </u>
110167	2.36		
13085	12		
17124	15.64	17124	2.0174 Cmf 09/07/10

## **Dart Aerospace Ltd**

	-		•								
W/O:			٧	VORK ORDER CHAN	GES				•		
DATE STEP		PRO	CEDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
			······································								
Part No:						CR: Yes No DQA: Date:					
Resolution:		olution:	Disposit	Closed:	osed: Date:						
NCR:		V	VORK OR	DER NON-CONFORM	IANCE (NC	R)					
DATE	STEP	Description of NC			ction B	Verific	ation	Approval	Approval		
	0121	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	e Section	on C	Chief Eng	QC Inspector		
		.8.									
				-							

Tage Tot2

DART AEROSPACE LTD	Work Order:	50099
Description: BRACKET	Part Number:	D3145-
Inspection Dwg: Rev:		Page 1 of 2

FIRST ARTICLE INSPECTION CHECKLIST								
		X First Arti	icle [	Prote	otype			
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments		
0.240	±0,010	0.240						
RO.250	±0,010	0,250				2PKS		
0,180	±0,010	0/180						
1.250	±0,010	1,249						
Z.960	±0,010	1.904						
Ø.221x 0.351		10 0.220x.341						
28,9°	+ 1/20	28.90	1			· ·		
0.108	±0,010	0,108			<u> </u>			
RO.330	+0,010	0.330						
0.125	±0,010	0.123	1			<del></del>		
RO.188	±0.010	0.1875				TYP		
0,125	±0.010	0.115				TVP		
1.636	±0,010	1,630						
95°	+ 1/20	95°						
740	+ 1/20	720						
RO.125	±0,010	0,125						
0,219	±0,010	0,219						
90	+ 120	90	1					
RO.387	±0,010	0.387	13/					
0,766	±0,06	0.766			<del></del>	REF		
0,250	±0,010	0.248						
1,370	±0,010	1,365						
0.700	±0,010	0.7600						
Measured by:	DIF	Audited by:	me	P	rototype App	roval: N/A		


Measured by:	Audited by:	Prototype Approval:	N/A
Date: 09/07/10	Date: 09/02/	/S Date:	N/A
Rev Date Change		Revised by	Approved
A New Issue		, KJ/JLM	





DART AERO	SPACE LTD				Work Order:	
Description:	-				Part Number:	
nspection Dwg	: Rev					Page Dof
	EIDG:	T ADTICLE II	ISPECT	<u> </u>		
	<del></del>	T ARTICLE IN		Proto		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
2,102	+0,010	2.702				
K0.31	± ලැගුීල	0.310				
R.1.26	±0,030	7,2Ce				
O,Zoo	+0,010	0,100				
9°	± 1/2°	90	V.			
2,636	7000	1.630	V			
		19 4				
		<del> </del>				
						·
						·
						-
		<del> </del>				<del></del>
<del>-</del>						<del></del>
		·				
						······································
	110 (110 110 110 110 110 110 110 110 110			<del></del>		



DESIGN DRAWN BY			DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA				
CHECK	ED	APPROVED	DRAWING NO.	REV. B			
71		1	D3143	SHEET 1 OF 1			
DATE			TITLE	SCALE			
03.02.06		02.06	BRACKET	1:2			
Α	0	2.04.24	NEW ISSUE				
В	0	3.02.06	ADD SLOTS; WIDEN TA	BS; 1.960 WAS 2.000			







D3145-1 BRACKET SHOWN. REPLACES PREMIER P/N B30-23000-25 (D3145-2 BRACKET OPPOSITE. REPLACES PREMIER P/N B30-23000-26)

## NOTES:

- 1) MATERIAL: 6061-T6/T651 (QQ-A-200/8 OR QQ-A-225/8) BAR (REF. DART SPEC. M6061T6B)
- 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1 POWDER COAT GLOSS WHITE (4.3.5.1) PER DART QSI 005 4.3 3) TOLERANCES ARE PER QSI 018 UNLESS OTHERWISE NOTED

- 4) ALL DIMENSIONS ARE IN INCHES
- 5) BREAK ALL SHARP EDGES 0.005 TO 0.015
- 6) ENGRAVE DART P/N AND LOGO AS SHOWN

## COPYRIGHT © 2003 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Dart	Aer	ospa	ıce l	_td
------	-----	------	-------	-----

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			,						•
Part No:		PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	Date: _	
Resolution:			Disposition: QA: N/C Closed: Date:						
NCR:		1	WORK ORD	ER NON-CONFORMA	ANCE (NC	R)			
DATE	0750	Description of NC	Corrective Action Section B			Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	&   Sect	ion C	Chief Eng	QC Inspector
					•				
								,	
							<del>, .</del>		

<sup>→</sup> H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE